


STATE OF UTAH DEPARTMENT OF NATURAL RESOURCES DIVISION OF OIL, GAS AND MINING

355 West North Temple 3 Triad Center, Suite 350 Salt Lake City, Utah 84180-1203 Telephone: (801) 538-5340 Fax: (801) 359-3940



ANNUAL REPORT OF MINING OPERATIONS

The informational requirements of this form are based on provisions of the Mined Land Reclamation Act, Title 40-8, Utah Code Annotated 1953, as amended, and the General Rules as promulgated under the Utah Minerals Regulatory Program. An operator conducting mining operations under a Notice of Intention must file an annual operations and progress report (FORM MR-AR) with the Division.

1.	General information			
	1.	Report Time Period: From (mo./yr.) 1-96 To (mo./yr.) 12-96		
	2.	DOGM File Number (Mine No): 5 /025/013		
	3.	Mine Name: THREE MILE # 1		
	4.	Mineral(s) Mined (or permitted to mine): 64PJUM ALABASTER		
	5.	Type of mine ☐ Surface Mine or ☐ Underground Mine		
	6.	Legal Description (Location of Lands Affected):		
		1/4,1/4, Section 28 , Township 405, Range 6 W		
		1/4,1/4, Section, Township, Range		
		1/4,1/4, Section, Township, Range		
	7.	Name of Operator or Company: Southwest STONE		
	8.	Permanent Street Address: 1959 S. HWY 89 A		
		City, State, Zip: KANAB UT 84741		
		Phone: 801-644-8877		
	9.	Company Representative (or designated operator):		
		Name: MIKE DETT ANGANTI		
		Title: CO-OWNER		
		Business Address: P.O 291		
		City, State, Zip: KANAS UT 84741		
		Phone: 801-644-8877		
		Please check if any of the above information has changed since previous year.		
II.	Min	ing and Reclamation		
	1.	Was the mine active during the past year? Yes ⋈ No □		
	2.	If active, how much ore or mineral was mined? 20 TON		

	3. How much additional acre	eage was disturbed during the past year? 1/20 Ac		
		or additional surface disturbances that occurred s description should include the type of work material moved.		
	EXCHURTE SOIL & WAS	TR GYP - SOIL REPLACED - RECKADED		
5.	How much acreage was reclain	med during the past year? Yno Ac.		
6.	description should include mer	n work performed during the past year. This thods employed, and an evaluation of the		
	BACK FILL W/ HO	E CRADE WY HOE		
7.	What is the total disturbed ac	reage at years end? <u>1/2</u> AC		
8.	Briefly summarize any mining and/or reclamation plans for the upcoming year.			
	CLAY SOILS WILL BR REPLACED AFTER LEDGE MATERIA			
	IS REMOVED - DISTURBANCE IS MINIMAL SITE WI			
	PRSERORD AT CLOSUKK	OF PROJECT WHENBURN THAT HAPPENS		
NOTE:	Section III., "Additional Inform	nation" applies only to large mining operations.		
III. Addition	nal Informa <mark>tion</mark>			
1.	An updated surface facilities map should be attached if there have been significant changes since to previous map was submitted.			
2.	Any monitoring results or other repintention should also be attached.	orts that are required under the terms of the approved notice of		
IV. Signatu	re Requirement			
I he	reby certify that the foregoing is	true and correct.		
	Name (Typed or Print):	MIKE DRITHMANTE		
	Title of Operator:	CO-OWNER		
	Signature of Operator:	MIKE DETTHMANTZ CO-OWNER MULL DETTHMANTS THE 21 1997		
	Date:	JAN 27 1997		